## SCS ENGINEERS

October 27, 2021 File No. 23212007.09

Ms. Maria Lammers Ohio EPA Southwest District Office 401 East Fifth Street Dayton, Ohio 45402-2911 Submitted Electronically

Subject: Village of St. Bernard Landfill MP-9 Weekly Contingency Monitoring Report

Dear Ms. Lammers:

Attached please find the results of the weekly contingency gas monitoring at MP-9, performed on behalf of the Village of St. Bernard at the closed St. Bernard Landfill on October 27, 2021.

MP-9 had an initial sustained reading of 38.6 percent combustible gas. The verification reading had a sustained reading of 33.5 percent. Contingency monitoring will therefore continue to be performed at MP-9 until sufficient data has been collected to meet the cessation criteria.

Following the initial and verification sampling for this contingency monitoring event, MP-9 was pumped for 20 minutes, at a rate of approximately 550 cc/min., using the GEM 5000. Approximately 10 casing volumes were removed from MP-9. Following the purge, the sustained combustible gas concentration was 12.6 percent. The falling methane concentration during the 20 minute purge indicates that the elevated concentration of methane is present in a small area, i.e. there is only a small volume of soil gas with an elevated concentration of methane present.

In addition to the monitoring of MP-9, a temporary bar punch test, BP-1, was performed 5 feet from the property fence in between MP-9 and the residence at 437 Bank Avenue. The bar punch did not detect any combustible gas.

Should you have any questions or comments, please contact the undersigned.

Sincerely,

Kandall C. Mills

Randall C. Mills, P.G. Senior Project Scientist SCS Engineers

RCM/JJW

cc: Nick Schapman, GHD Tom Paul, Village of St. Bernard Jonathan Stuchell, Village of St. Bernard Chuck DeJonckheere, R.S., Hamilton County Public Health

James J. Walsh, P.E. Principal SCS Engineers

Encl.



## Compliance Probe Monitoring Form for St. Bernard Landfill

Date:	10/27/21				Sampler:	Randall Mills		
Instrument	GEM 5000				Weather:	clear, calm		
Calibration Prior to Sampling: Yes					Ambient Air Ter	emperature (°F): <u>45</u>		
Calibration Gas:	CH <sub>4</sub> 15%, CO <sub>2</sub> 15%, O <sub>2</sub> 4%				Barometric Pressure (in Hg):		29.50	
Recalibration:	No				Relative Humidity (%):		78	
							Depth to	
							Top of	
						Depth to	Screen	
			Gas			Water Level	(feet	0
			Pressure			(feet below	below	Open
	Start	Stop	(inches	Initial CH <sub>4</sub> (%	Sustained CH <sub>4</sub>	ground	ground	Screen <sup>#</sup>
Probe ID	Time	Time	water)	by Volume)	(% by Volume)	surface)	surface)	(feet)
MP-9	10:50	10:51	-0.01	37.4	38.6	7.51	2	5.5
	10.55	10.50						
MP-9 validation	10:55	10:56	0.03	37.3	22.5			
MD 0 post purgo	11:19	11:20	0	9.4	12.6			
MP-9 post purge	11.19	11.20	0	9.4	12.0			
BP-1	11:29	11:30	0.01	0	0			
	11.20	11.00	0.01	Ŭ	Ŭ			
Notes: Temporary BP-1 is located 5 feet from the property fence in between MP-9 and the								
residence, in the back yard of 437 Bank Avenue.								
Signature: Randell C. mille								

<sup>#</sup> A zero or negative value indicates that the probe is watered in.