SCS ENGINEERS

May 16, 2019 File No. 23212007.07

Ms. Maria Lammers Ohio EPA Southwest District Office 401 East Fifth Street Dayton, OH 45402-2911 **Submitted Electronically**

Subject:

Saint Bernard Landfill, 2019 Annual Recalibration of CGIs

Dear Ms. Lammers:

This letter presents the results of annual recalibration of Combustible Gas Indicators (CGIs) that are installed in residences adjacent to the closed Saint Bernard Landfill in compliance with the approved Explosive Gas Monitoring Plan.

SCS requested access to the eight homes that have CGIs from the owners and/or residents by letter and/or by email to schedule the annual calibration of the CGIs for the afternoon of March 20, 2019. Six homes had their CGIs calibrated on March 20, 2019 and one home had their CGI calibrated on March 28, 2019. The calibrations were performed by Randall Mills of SCS. Field notes for each recalibration are summarized in the table below. All the CGIs have a set point of 10,000 ppm (1 percent by volume), with the exception of the Zeigler property (441 Bank Avenue) for which the CGI remains at a set point of 2,000 ppm (0.2 percent by volume).

Address (Bank Avenue)	Date	Approximate Start Time (p.m.)	CGI in Operation on Arrival	Sensor Replacement Required	Calibration Completed (10,000 ppm)	Verification Test Successful		
421	3/20/19	14:10	No CGI was present. Installed spare CGI.	n/a	Yes	Yes		
425	As of the date of this report, SCS has not been able to make contact with the owner of this residence (as was the case last year). SCS will continue to attempt to perform the calibration and will submit a supplemental report if the calibration is performed.							
426	3/20/19	18:20	No, not plugged in.	No	Yes	Yes		
429	CGI removed in 2017 per resident request.							
433	3/28/19	16:45	Yes	No	Yes	Yes		
437	3/20/19	17:05	Yes	No	Yes	Yes		
440	3/20/19	17:30	Yes	No	Yes	Yes		
441	3/20/19	17:20	Yes	No	Calibrated to 2,000 ppm.	Yes		



					Calibration	
Address		Approximate	CGI in	Sensor	Completed	Verification
(Bank		Start Time	Operation	Replacement	(10,000	Test
Avenue)	Date	(p.m.)	on Arrival	Required	ppm)	Successful
Avenue) 444		(p.m.) r of this residence				Successful

The CGIs that were found to be unplugged were plugged in to perform the calibration and were left plugged in after the calibration.

Please contact the undersigned if you have any questions.

Sincerely,

Randall C. Mills, P.G. Senior Project Scientist SCS Engineers

James J. Walsh, P.E. **Project Director** SCS Engineers

RCM/JJW

John Estep, Mayor, Village of St. Bernard CC Tom Paul, Service Director, Village of St. Bernard

Nick Schapman, GHD

Randall C. Mills

Chuck DeJonckheere, Hamilton County Health Dept.